

**BETTER BOLTING, INC.**  
**50IBT**  
**PRESSURE/TORQUE CONVERSION CHART**

| PRESSURE IN | TORQUE |          |
|-------------|--------|----------|
|             | PSI    | FT. LBS. |
| 1000        | 5155   | 6989     |
| 1200        | 6224   | 8438     |
| 1400        | 7293   | 9888     |
| 1600        | 8362   | 11337    |
| 1800        | 9431   | 12787    |
| 2000        | 10500  | 14236    |
| 2200        | 11559  | 15672    |
| 2400        | 12618  | 17107    |
| 2600        | 13677  | 18543    |
| 2800        | 14736  | 19979    |
| 3000        | 15795  | 21415    |
| 3200        | 16856  | 22853    |
| 3400        | 17917  | 24292    |
| 3600        | 18978  | 25730    |
| 3800        | 20039  | 27169    |
| 4000        | 21100  | 28607    |
| 4200        | 22171  | 30059    |
| 4400        | 23242  | 31512    |
| 4600        | 24313  | 32964    |
| 4800        | 25384  | 34416    |
| 5000        | 26455  | 35868    |
| 5200        | 27504  | 37290    |
| 5400        | 28553  | 38712    |
| 5600        | 29602  | 40134    |
| 5800        | 30651  | 41557    |
| 6000        | 31700  | 42979    |
| 6200        | 32843  | 44529    |
| 6400        | 33986  | 46078    |
| 6600        | 35129  | 47628    |
| 6800        | 36272  | 49178    |
| 7000        | 37415  | 50727    |
| 7200        | 38488  | 52182    |
| 7400        | 39561  | 53637    |
| 7600        | 40634  | 55092    |
| 7800        | 41707  | 56546    |
| 8000        | 42780  | 58001    |
| 8200        | 43879  | 59491    |
| 8400        | 44978  | 60981    |
| 8600        | 46077  | 62471    |
| 8800        | 47176  | 63961    |
| 9000        | 48275  | 65451    |
| 9200        | 49345  | 66902    |
| 9400        | 50415  | 68352    |
| 9600        | 51485  | 69803    |
| 9800        | 52555  | 71253    |
| 10000       | 53625  | 72704    |